

CP RL6s November 2022

11/8/2022	Labs canceled at request of phlebotomy; labels left in pt room and used for a hard stick. Orders canceled when received in lab. Not tested.
11/9/2022	Wrong ordering provider entered
11/10/2022	CBC and CMP labels placed on wrong tubes in CP; CBC spun on track
11/11/2022	Name misspelled at Vista order entry
11/12/2022	Incorrect tests ordered
11/14/2022	BNP placed on packing list to Special Heme. Error not found until stability expired.
11/15/2022	Sample not processed within stability
11/15/2022	Spun TEG
11/17/2022	Spun CBC
11/27/2022	Spun CBC
11/28/2022	DOB on Helms samples and requisition mismatched Beaker DOB. Not caught before testing completed.

CP RL6s December 2022

12/6/2022	Swab tubed to floor in dirty/blood contaminated bag
12/6/2022	Code stroke lavender top/CBC spun
12/6/2022	Urine hold for culture not poured off in CP. When culture reflexed, no sample was available for testing.
12/7/2022	CMP sample lost between CP and track
12/14/2022	HPTT sample missing. Not received with BMP sample collected at same time.
12/14/2022	Patient registered under wrong X account
12/16/2022	BMP and Mg label found in biohazard bag trash. Tests were not completed. Should have been shared with Phos sample collected at same time.
12/22/2022	Peds ED chemistry samples not scanned, delayed results
12/22/2022	Incorrect test ordered as add-on
12/26/2022	Fresh (not in formalin) tissue sample found in room temperature Surg Path bin. Had been collected on 12/24/22 and discovered on 12/26/22. Path resident was not paged on 12/24/22 and sample was not refrigerated.
12/29/2022	Total volume for 24-hour urine entered incorrectly. One of two jug volumes entered. Need to add both volumes for total volume.