

### CP RL6s January 2023

1/5/2023	Sendout test not processed correctly
1/12/2023	Pedi green sample lost between CP and chemistry
1/23/2023	Nurse given wrong tube type information for sendout test; sent wrong tube; redraw required
1/23/2023	Urine Na/K not poured off for chemistry - went on UA analyzer and sent for redraw
1/24/2023	Lav and gold labels switched for XVIDT tubes; CBC spun on track
1/26/2023	Gold top found in crevice of tube station unspun >2 hours, unsuitable for testing
1/27/2023	Ferritin added to pediatric patient's sample. Test routed to LMC Lab (23L accession). Test not performed. Out of stability when provider called to inquire.
1/30/2023	Short CBC sample spun