

CP RL6s June 2023	
6/7/2023	Labcorp specimen put on packing list to HLA. Sendout test not completed for transplant patient prior to surgery.
6/8/2023	lavender top for sendouts spun in error
6/12/2023	Specimen requisition and labels did not match; ordered in WakeOne, labeled in CP. Bad ID. Results removed, provider notified, charges credited.
6/13/2023	Specimen mislabeled in CP. Patient Messick's label placed on patient Thomas's blood.
6/15/2023	Short CBCD spun
6/16/2023	Breast tissue not in formalin received by tube station after hours. Pathologist not notified for 3 hours. Specimen needs to be in formalin within 1 hour.
6/21/2023	Short CBCD spun
6/26/2023	Vancomycin Peak collected from order inquiry. Specimen was actually a vancomycin trough.
CP RL6s July 2023	
7/5/2023	Vancomycin peak ordered from requisition. Test requested was vancomycin random
7/12/2023	unspun gold top put on track in white/spun rack.
7/17/2023	Allergy gold tops not put in allergy rack. Lost between CP and Clemmons. Not put on packing list to Clemmons.
7/18/2023	unspun gold top put on track in white/spun rack.
7/21/2023	orders in signed and held status - reordered in CS. Ordering provider did not want labs run at this time.
7/25/2023	Body fluid chemistry orders canceled, not re-ordered correctly. Provider called to question why orders were canceled. Tests re-ordered and processed at that time.
7/28/2023	Gold top relabeled (original label upside down). New label was placed on the wrong patient specimen / Bad ID.