

**IMPORTANT NOTIFICATION:****Technical Bulletin: V-Docs Procedure Update Following Modification (MOD) 93 Installation on VITROS® 5600 Integrated and 3600 Immunodiagnostic Systems****Date Issued** February 18, 2016**New Technical Bulletin**

New Technical Bulletin	Pub. No.	Pub. Date
V-Docs Procedure Update Following MOD 93 Installation	J56051xx*	2015-11-24

\*xx denotes language

**Summary**

The enclosed Technical Bulletin provides information on a procedure update for moving the Signal Reagent Metering and MicroWell Wash arms to their maintenance positions when performing maintenance on your VITROS® 5600 and 3600 Systems after MOD 93 has been installed. MOD 93 is a modification to improve the performance and reliability of the WELL WASH NOZZLE on these systems.

Your Technical Service Representative will contact you to schedule installation of MOD 93 on your systems when the MOD becomes available which is anticipated to be in February 2016.

In the future, the information contained in the Technical Bulletin will be added to V-Docs. Please store the Technical Bulletin with your user documentation until V-Docs has been updated.

**Contact Information**

If you have any technical questions regarding this notification, please contact the Ortho Clinical Diagnostics Technical Solutions Center at 1-800-421-3311.



Marie-Claude Renaud  
Laboratory Specialist Manager

Enclosure:

Technical Bulletin: (Pub No. J56051\_EN)