


Detection of Vancomycin Resistance in Staphylococcus aureus Flowchart (LTR79355)

Edit Approved By: Van der Walt, Peet (08/30/2023)

Revision: 5.00



#2134 This isolate has elevated MIC to vancomycin and may experience treatment failure. Consider expert consultation.
Note: Do NOT add 21345 to MRSA Screen isolates from nose or groin specimens. For other sites, consult Microbiologist.
#A280 Vancomycin results confirmed by two methods.
#va11 This isolate exhibits resistance to vancomycin.
#A299 This isolate exhibits resistance to vancomycin and has been sent to a reference laboratory for Van gene testing

Note 1: Use actual Etest MIC not doubling dilution value.
Note 2: If Presumptive was added to vancomycin preliminary results: Remove Presumptive and replace with **#A280** and report vancomycin Etest MIC.