Procedure Change/Revision (IMM 36-C)

Procedure:

A₁C

Change/Revision:

All sample barcodes that fail to read appear in Instrument Menu as "EMPTY". Delete "EMPTY" from Order field and manually scan barcode, then Save. Before verification of result, review chromatogram and confirm that value matches sample that did not read.

Date of Revision:

3/23/2012

Director Signature/Date:

Technologist Signature/Date: