Central Processing RL6s September 2021

	issing KLOS September 2021
9/1/2021	Sample for UA and Urine Na/K/Creatinine - UA sample was not sent to bench for testing. All of sample was aliquoted for chemistry. Empty original conical tube with UA label was found in Spin trash.
9/4/2021	Sample for JAK2 was found in room temperature Special Heme bin 2 days after received in lab. This should have been stored refrigerated (in Sendouts fridge). Checking bins is part of daily Spin maintenance.
9/5/2021	Tracheal aspirate was found in Surgical Pathology bin over 24 hours after specimen was dropped off at window. Sample was for micro. Order was entered for the sample 4 hours after it was dropped off at window. No specimen issues email was sent regarding order needed. Micro accepted sample but testing was delayed.
9/9/2021	CareEvolve orders did not cross on a patient. Samples were placed in hold bin with no specimen issues email sent. Samples did not get tested. Not found until provider called looking for results 6 days later when stability exceeded for testing. Samples had to be redrawn.
9/9/2021	CareEvolve orders did not cross on a patient. Samples were placed in hold bin with no specimen issues email sent. Samples did not get tested. Not found until provider called looking for results 6 days later when stability exceeded for testing. Samples had to be redrawn.
9/9/2021	CareEvolve orders did not cross on a patient. Samples were placed in hold bin with no specimen issues email sent. Samples did not get tested. Not found until provider called looking for results 6 days later when stability exceeded for testing. Samples had to be redrawn.
9/15/2021	Peds ED urine sample went straight to micro, all sample was poured off as hold for culture, and UA was missed.
9/16/2021	3 of 4 samples from a packing list were received in lab. The fourth sample was not received and no specimen issues email sent. Test not performed and not caught until provider called for results.
9/20/2021	CSF was found in the room temperature Cytology bin. Dated 9/17/21, in bin 3 days at RT. Should have been in refrigerator. 2 urine samples from a packing list were not scanned in lab (5 of 7 samples received). One of the samples was a UPC, and we scanned in a
9/28/2021	UA on the same patient. If we had reconciled the packing list we could have also run the UPC. No specimen issues email was sent for the missing urine sample. Unspun sample placed in spun brick. Results verified before caught.
9/29/2021	Sample spun and retested. Results corrected.

	Body fluid accessioned under wrong orders (two sets of orders: one for
	paracentesis and one for thoracentesis). Paracentesis sample
9/29/2021	accessioned under thoracentesis orders.