

### Central Processing RL6s December 2021

12/2/2021	Gold top tube lost between CP and Chemistry
12/2/2021	Ammonia found in Spin trash, not found until out of stability
12/2/2021	PT/PTT sample found in Spin trash. Sample had not been scanned. Was accepted for testing by coag.
12/2/2021	Non-cardiac CRP was added to a pedi green top bullet. Not found until sample already verified.
12/2/2021	No fax number entered for POPL with "provider not in system" used as ordering provider. Provider did not get results until he called to request them a week later.
12/3/2021	Synovial fluid cell count not processed. Not found until physician called 2 days later. Sample had gone straight to micro without CP completing a worksheet.
12/6/2021	Medical genetics lavender tube centrifuged and aliquoted. Lavender tubes are whole blood.
12/9/2021	CBC was centrifuged
12/13/2021	CBC was centrifuged
12/14/2021	UA not poured off, all sample used for urine chemistry testing.
12/17/2021	Blue top tube for PLT Count was spun in error
12/20/2021	BMP found in tube room trash beyond stability. Had to be redrawn.
12/20/2021	6 CBCs centrifuged
12/20/2021	Urine culture not poured off; cap not secured on cup; sample spilled in bag between CP and micro; unacceptable for culture.
12/20/2021	Blue top tube for PLT Count was spun in error
12/22/2021	Blood from cath lab received with no orders. When we called cath lab, they were in the process of entering orders. Samples not processed for 1.5 hours after received. Results delayed.
12/23/2021	Routine urine processed and resulted under 24-hour urine order
12/23/2021	CBC was centrifuged
12/27/2021	Dropped and broke a pediatric blood culture sample
12/27/2021	Sample mislabeled in CP