

Central Processing RL6s April - May 2023

4/5/2023	ED specimen not processed during planned downtime. Delayed results.
4/5/2023	Critical ED specimen not processed during planned downtime. Delayed results by 4 hours.
4/7/2023	Random urine processed under 24-hour urine order.
4/12/2023	UA canceled as duplicate. Two separate specimens sent for analysis (not a duplicate order)
4/17/2023	Unspun gold top found on accessioning floor past stability
4/20/2023	Lavender top mislabeled with another patient's CBC label
4/24/2023	Unspun gold top placed in centrifuge bypass (white) rack
4/24/2023	Unspun gold top placed in centrifuge bypass (white) rack
4/25/2023	Helms Home Care orders placed on wrong patient in Beaker. Specimens tested and results released to wrong chart.
4/27/2023	Urine culture scanned/received in CP. Lost between CP and micro.
5/5/2023	CBC spun in CP
5/6/2023	Unspun gold top placed in centrifuge bypass rack
5/9/2023	CBC spun in CP
5/11/2023	UA orders missed, not scanned from packing list. When found, specimen past stability.
5/12/2023	U osmo order missed, not scanned from packing list. When found, specimen past stability.
5/12/2023	UPC order missed, not scanned from packing list. When found, specimen past stability.
5/15/2023	UPC in conical tube, label not reprinted/not aliquoted. Went on UA analyzer and had to be recollected.
5/16/2023	Urine Albumin - two labels printed in CP. Two aliquots poured off. Results did not match on two specimens. Chemistry pulled original specimen and poured off new sample. Corrected results.
5/17/2023	Urine in gold top SST with Serum Osmolality label. Not caught at receipt. Chemistry tests added to the tube and resulted before error caught. Results had to be corrected.
5/22/2023	Urine pregnancy received in conical tube. Label not reprinted. Not checked in Spin or UA. Ran on UA analyzer and had to be recollected.
5/22/2023	CBC spun in CP
5/30/2023	Cytokine delivered Stat at 1133, not scanned in lab until 1251. Past stability.