	Click box and type needed changes/additions:
	☐ Section Not Applicable
	□ Its changes – New priority code has been created in both TESTAR and LIVE and
	is ready to use as appropriate (Mike Boyer)
	□ Reference range change/addition
Laboratory IT	☐ Technical Failure change/addition
section:	☐ Critical Value change/add
	☐ Text comments needed
	□ Specimen collection instructions
	□Need to monitor TAT
	\square CPT code for tests(s)
	Women's Hospital Phlebotomy Team and Laboratory Staff must recognize Type and Screen orders with a TAT2HR priority as needing to be <u>collected</u> , <u>received in lab</u> , <u>tested and resulted within 2 hours</u> .
	If blood bank techs are unable to complete testing within the expected 2 hour TAT
	because of antibody problems or special blood needs, techs should inform the
	patient's caregiver. Document in a BB comment the name of the informed caregiver,
	the date, time, and tech initials.
	Also provide the caregiver with an approximate time testing should be completed and blood products available if needed.
Technical Staff	olova producti arazava.
Update:	Other Cone Health campuses: The TAT2HR priority is intended for OB Type and
* .	Screens ordered at Women's Hospital however if a Type and Screen order with a TAT2HR priority is encountered at another Cone Health laboratory, Phlebotomy staff and blood bank staff should recognize the TAT2HR priority, collect and complete testing within 2 hours.
	See attachment 1: LIS specimen label showing a Type and Screen ordered with TAT2HR priority.
	See attachment 2: CHL Clips and Notes about TAT2HR priority
STOP Initiator:	Teresa Wright
	Quality Department will obtain signature:
Medical Director	Sara C Ruhnus M. D.
Signature:	Syana C. Tanasa C.