

Name: GMS-Schmidt #2

Type: Special
Modified: 2005/09/20

Origin: Copy
Author: Patti

Description: Lighten up more

Step	Dispense Liquid	Volume (mL)	Time (secs)	Heater (C)	Mixes	Aspirate	Waste
001	None	-	0	Off	0	On	Water Soluble Waste
002	Sodium Chromate - GMS	1.00	0	Off	0	Off	
003	Perchloric Acid - GMS	1.00	600	45	3	Off	
W1	Wash Solution	3.00				On	Combined Dye Waste
W2	Wash Solution	3.00				On	Combined Dye Waste
W3	Wash Solution	3.00				On	Combined Dye Waste
WF	Wash Solution	3.00				On	Combined Dye Waste
004	Sodium Bisulfite - GMS	1.00	500	Off	2	Off	
W1	Wash Solution	3.00				On	Water Soluble Waste
W2	Wash Solution	3.00				On	Water Soluble Waste
W3	Wash Solution	3.00				On	Water Soluble Waste
WF	Wash Solution	3.00				On	Water Soluble Waste
005	Silver Nitrate - GMS	1.00	40	Off	0	Off	
006	Methenamine Borate - GMS	1.00	400	62	3	Off	
007	Wash Solution	2.00	0	Off	2	Off	
W1	Wash Solution	3.00				On	Trace Metal Waste
W2	Wash Solution	3.00				On	Trace Metal Waste
W3	Wash Solution	3.00				On	Trace Metal Waste
WF	Wash Solution	3.00				On	Trace Metal Waste
008	Gold Chloride - GMS	1.00	500	Off	1	Off	
W1	Wash Solution	2.00				On	Trace Metal Waste
W2	Wash Solution	3.00				On	Trace Metal Waste
WF	Wash Solution	3.00				On	Trace Metal Waste
009	Sodium Thiosulfate - GMS	1.00	500	Off	2	Off	
W1	Wash Solution	2.00				On	Water Soluble Waste
W2	Wash Solution	3.00				On	Water Soluble Waste
WF	Wash Solution	3.00				On	Water Soluble Waste
010	Light Green - GMS	1.00	10	Off	2	Off	
W1	Wash Solution	3.00				On	Combined Dye Waste
W2	Wash Solution	2.00				On	Combined Dye Waste
W3	Wash Solution	2.00				On	Combined Dye Waste
W4	Wash Solution	2.00				On	Combined Dye Waste
W5	Wash Solution	2.00				On	Combined Dye Waste
WF	Wash Solution	3.00				On	Combined Dye Waste