

Indianapolis, IN 46202

Standard Operating Procedure Manual (SOP) – Transfusion Medicine

Deviation From SOP

Procedure #:

BBQA - F001Quality Assurance

Manual: Original Effective:

04/27/09

Revised: Revision Effective: 08/04/2011

04/21/2011

Page 1 of 1

Date:_	6/10/21_	Affected SOPs: MTP and Platelet Inventory
Sample	es Involved:_	Trauma and Patients with Platelet orders for multiple units
1)	low inventory Revision to M	or currently, AHC BB is implementing: MTP process for 3 RBC, 3 Plasma and 1 platelet every other atelet order for more than 1 platelet.
Trauma		fied of lower product volumes in the MTP cooler and BB Medical Team will be icians for multiple orders.
	Jayanna Slaty logist/Supervi	ren July Wally 6/10/21 Approved By